

TROUBLE SPOT -- These are the mechanisms that malfunctioned early in the Apollo-14 flight. Program officials and engineers surmised that "capture latches" on the tip of the command ship's probe assembly (left) failed to operate when inserted into the locking collar of the lunar lander. (71-846)

