

(20511)F6

ORBITAL PICTURES -- The Viking-1 landing was delayed when orbital pictures showed the prime target area was not as smooth as earlier photography had indicated. These views show the Argyre Plains (left) and the crater Yuty (right) near the original landing site. (76-1842)

