

SURVEYOR'S IMPRESSION ON THE MOON -- The fine texture of the moon's surface and the depression made in it by one of the three landing pads of Surveyor I show in the narrow-angle photo. Grains of 0.5mm diameter can be resolved in the disturbed surface next to the pad, according to project scientists at the Jet Propulsion Laboratory in California. A camera test pattern disk is mounted on the spacecraft's leg. This is one of 10,338 pictures received from Surveyor during its 12 days of operation before closing down June 13 for the two-week lunar night. The spacecraft was launched May 31 from Cape Kennedy in Florida and made a "soft" landing on the moon June 2. (66-1831)

